



Maintenance and Safety Directive

Reference:

Replacement of all wire ropes, bolts, connecting pins and or shafts associated with the power belay and cable ends.

Introduction:

The following **ANNUALLY** replacement schedule should be adhered to in order to maintain the structural integrity of the Rascal Rocket structure

Background:

This directive is for all 16' and 24' mobile and or stationary Rascal Rockets manufactured by Spectrum Sports Int'l, Spectrum Sports Inc., Action Amusement and Rebound Action Sports.

Action:

Replace all wire ropes with Spectrum Sports International certified wire rope.

Replace all bolts that secure all pulleys with new ones the same size. Replace grade 5 bolts with grade 8 if grade 5 bolts were used. This includes the pulleys at the top of the ride as well as on the pulleys in the power belays.

Replace all pins and or bolts that secure the power belay cylinder to the power belay weldments.

Replace the shaft that secures the cable to the carriage which the seat rest on.

Replace the bolts used to connect the cable ends to the carriage on the power belays.

Replace the bolts used to secure the power belay to the upper frame.

Call us if you have questions concerning this letter.

Frequency:

This replacement schedule should be followed annually for the life of the ride.

Spectrum Sports Int'l
Phone: 435-792-3883
Email: Service@spectrumsports.com

